





Photograph 1 –Cell 2 Backfill activities completed



Photograph 2 – Installing centerline sheet pile under Lyman Street Bridge in Cell 3



Photograph 3 – Excavation activities in Cell 3



Photograph 4 – Riverbank excavation activities in Cell 3



Photograph 5 – Installation of Shotcrete under Lyman Street Bridge in Cell 3



Photograph 6 – Excavation activities in Cell 4



Photograph 7 – Backfill activities in Cell 4



Photograph 8 – Backfill activities in Cell 4